

Summary LANXESS TA2020 COVID-19 measures

1. BASIC rule COVID-19: 1. Stay home if you're sick – 2. Social distancing (> 1,5 m) – 3. Wash your hands thoroughly.
2. Wearing a face mask is obligatory : Face masks to be provided by contractor + LANXESS will provide 2 face masks/employee
3. Temperature scanning at site entry
4. Measurements to limit close contact: walking at right side – priority when badging OUT & coming upstairs
5. Extra facilities in the plants to wash your hands
6. Additional measures to increase social distancing in sanitary and refectory units (spreading times)
7. Clustering lunchbreaks & use of plexiglass screens to increase capacity of refectory units
8. Identifying additional COVID-19 measurements on job level (# employees + specific measurements)
9. Indicate single point of contact to handle work permits, renting of equipment & PPE in safety shops, ...
10. Increase frequency of cleaning tools and machinery (esp. in case of common use !)
11. Wearing gloves should be encouraged (surface touching protection) + wash hands after removing gloves
12. Specific measurements on contractor level to facilitate possible contact tracing.